





to reduce stress & emi.  
high current inductors are expensive.  
attach one yourself  
-6uL  
fet will be fighting for its life regardless



super caps are a cheaper alternative but I think too dangerous

Sheet: /	
File: HC ohm tester.kicad_sch	
<b>Title:</b>	
Size: A4	Date:
KiCad E.D.A. 9.0.0	Rev:
	Id: 1/1