



the GPIO15 isn't grounded which it should,

the circuit was unstable and the MCU only booted proper when a semi-working DRV8825 driver was connected to first or second slot

Sheet: /  
File: Circuit\_final\_design.kicad\_sch

**Title:**

Size: A4  
KiCad E.D.A. 9.0.0

Date:

Rev:

Id: 1/1