



IO ALT1 ALT2 ALT3

11# #PWM 8/16bit
10# #PWM 16bit
9# #PWM 16bit
8

13 #PWM 10bit

12 #PWM Hi-Speed
7 #PWM Hi-Speed
6# #PWM Hi-Speed
5# #PWM Hi-Speed
4# #PWM 8bit
3# #PWM 8bit
2# #PWM 8bit
1# #PWM 8bit

+A11
+A10
+A9

+PWM COMPL I010

+A7
+AINO
+A8
+A6

PWM 16bit COMPL D6

