




To do
 check component values tick
 fusing, reverse pol, dual 5v connect
 check layout of major components
 check board out and in pads
 add test points?
 filtering?
 Inverting signal?
 status LEDs?
 Buzzer?
 check external components

Voltage meter?

Michael Spurdle	
Sheet: /	
File: stm32 flight control board 1.kicad_sch	
Title: STM32 Flight controller	
Size: A4	Date: 2022-04-07
KiCad E.D.A. 9.0.0	Rev: Id: 1/2



Sheet: /Connectors/
File: connectors.kicad_sch

Title:

Size: A4 Date: 2022-05-06

KiCad E.D.A. 9.0.0

Rev:

Id: 3/2